

Plans

Maps loaned to H. M. Bradford.

In two cases. -

A.S.

Plan of Lots made by McCully July 1900. -

Blue print of same. -

- 1 Profile Blue print made by McCully Engineering Co. -
- 2 " " " " " " " " " " " "
- 3 " Block 2 " " " " " " " " " "
- 4 " " 5 " " " " " " " " " "
- 5 " " 1 " " " " " " " " " "
- 6 " - Profile - several of them.
- 7 Areas - Plan in outline. McCully. 1901. - ✓
- 8 " Blue print " " " " " " " " " "
- 9 " " " " " " " " " " " "
- 10 " " " " " " " " " " " " showing computation cubic yds. -

Photographed. -

Approximate quantities.

Str. A. -	16630 cubic yds. cut. -
" B. -	2910
" C. -	3246
Block 1 -	0000
" 2 -	5325
" 3 -	6340
" 4 -	29000

In ink. -	10500
	2964
	2535 (2535)
	365
	11405
	35654
	3443

Total 78656.72

Total 63481 Barrow Pit

64169
11486
75655.72

List of maps loaned to H. M. Bradford, July, 1900

Box 5, Folder 3

Darlington Family Papers, 1753-1921, DAR.1925.01, Darlington Collection, Special Collections Department, University of Pittsburgh

